



1999 TBM 700B
Serial Number: 149 Registration: N800GS
Price: \$1.2mm

AIRFRAME

Total Hours: 3250 Hours
Socata Maintenance Program

ENGINES/PROPELLER

Pratt & Whitney PT6-64
TBO: 3500 hours
3250 hours since new
JSSI engine program fully paid for 100% coverage

Hartzell 4 Blade Constant Speed Reversing and Feathering Propeller
Model: HC-E4N-3
Time Since Overhaul: 450 Hours

INTERIOR

Six place aircraft with tan leather seats, tan ultra-suede headliner and sidewalls, matching carpet and high gloss wood trim. Updated interior January 2019. Cabin seating for four passengers in a VIP club configuration with executive table. Refreshment storage areas and entertainment console located mid cabin between crew and passenger seats.

EXTERIOR

New paint January 2019 by Rose Aircraft Services Inc.

ADDITIONAL EQUIPMENT & HIGHLIGHTS

ADS B Out upgrade
RVSM Capable
Freon Air Conditioning
Large Entry Door
Yaw Damper
Known Ice Certified
Pulse Light Anti-collision System
Only three US Owners since New
No damage history

AVIONICS

ADS B Out avionics upgrade
RVSM Capable
Honeywell EFIS 40 EADI and EHSI
Garmin GNS530W
Garmin GNS430
BF Goodrich Skywatch TAS
KFC 325 Digital Autopilot and Yaw Damper
Autopilot Altitude Pre-Select
Dual KT71 Mode-C Transponders
KN63 DME
KR87 ADF
RDR 2000 Radar
WX 1000 Stormscope
PMA 8000 PS Engineering Audio Select Panel
KRA405 Radar Altimeter
Airtex ELT 1000
Shadin Engine Trend Monitoring System

MAINTENANCE DETAILS

Excellent Maintenance History
Socata Service Center Maintained



Aircraft hours subject to change. Specifications subject to verification upon inspection.
Contact: Richard Hodkinson Richard@AeroAdvisors.com - (818) 988-JETS (5387)